

UT-058-45N

Inspection Date: 7/6/90

Inspector: Linda L. Jackson

Operator: Richard Hilyard

Claim: Grant #1 & #2  
(UMC 263241-263242)





Photo 1 & 2. Photo taken from north end of disturbed area.  
T. 21 S., R. 1 E., Section 15, NW1/4NW1/4.

UT-058-45N



Photo 3. Settling pond 40 ft by 40 ft.



Photo 4. Discarded equipment and trash -- boards, glass, cans, old fence

UT-058-45N




Photo 5. Pit, 4 ft in diameter and 4 ft deep. Discarded debris.



Photo 6. Trommel and discarded equipment.

UT-058-45N




Photo 7. Oil spill, 3 ft by 10 ft.



Photo 8. Pit, 4 ft long X 2 ft wide X 2 ft deep.

UT-058-45N



Photo 9. Road cut marked as new road on amended map for UT-058-10N. Road 550 ft long. 250 ft of the road has inside cuts greater than 3 ft.



Photo 10. View to the NW. Constructed road and dozer.

UT-058-45N



Photo 11. General view of disturbed area. Settling pond to center left. Debris scattered throughout area.



Photo 12. View to the NW. Photo of ridge on north side of disturbed area. Note open cut 30 ft X 80 ft. Source of clay liner material.